

Beacon Hill[™] Flagstone 60mm



1-800-UNILOCK | UNILOCK.COM

BEACON HILL[™] FLAGSTONE 60mm

ENDURACOLOR



ALMOND GROVE FUSION



OAK BROWN FUSION

PRODUCT ATTRIBUTES

Visual Appearance	Gentle surface clefts and clean edges.	
Finish	Flag/Riven finish.	

PRODUCT SPECIFICATIONS



LARGE RECTANGLE 15 x 22 ⁷/₁₆ x 2³/₈" 380 x 570 x 60 mm



SQUARE 15 x 15 x 23/8" 380 x 380 x 60mm



SMALL RECTANGLE 7 ½ x 15 x 2¾" 190 x 380 x 60mm

3 UNIT RANDOM BUNDLE

EDGE DETAIL



ROUNDED EDGE

BUNDLE CONFIGURATION




LAYING PATTERNS



RANDOM A 40% Large Rectangle, 40%

BEACON HILL B



RANDOM B 40% Large Rectangle, 40% Square, 20% Small Rectangle Square, 20% Small Rectangle



GRANITE FUSION



TUSCANY

RECOMMENDED SAND



Gator G2 MAXX Sand

Setting time - 15 mins

Sets above 32° F/ 0° C Can be applied if rain is expected

- (min. 1 hr)
- Dust free and haze free
- Requires only one watering Four colours: Beige, Grey, Black and

lvory Coverage:

eerelage.									
Colour	Narrow Joints	Wide Joints							
Beige, Grey, Ivory <i>50lb. bag</i>	65-85 sqft	22-42 sqft							
Black 50lb. bag	58-76 sqft	20-38 sqft							

RECOMMENDED SEALER



Gator Natural Look Sealer

- Water-based Zero gloss finish
- Multi purpose
- Rain safe after 24 hours Coverage:

	ug	с.	

Size	Area
3.78 L / 1 U.S. gal.	175 sqft
18.9 L. / 5.28 U.S. gal.	875 sqft

TECHNICAL INFORMATION

ASTM C936 Standard Specifications for Solid Concrete Interlocking Paving Units

Conforms to:

- C140 for Absorption 4% avg 5% max
- Compressive Strength > 8,000 PSI avg.
- C1645 for Freeze-thaw Durability
- C418 for Abrasion Durability

Dimensional Accuracy +/- 3mm

Test results available upon request

Meets the U.S. Architectural & Transportation Barrier Compliance Board Slip-Resistance Surfaces Advisory Guidelines

TECHNICAL ADVANTAGES

ENDURACOLOR

Refined surface and long-lasting colour

PEDESTRIAN FRIENDLY

Not recommended for vehicular

PRODUCT DATA

SOLAR REFLECTIVE INDEX (SRI) TESTING DETAILS

Product	Solar Reflectance	SRI
Tuscany	0.39	44 44 SRI

LEED INFORMATION

Materials & Resources: LEED V4:

Building Product Disclosure and Optimization

Sourcing of Raw Materials - Sourcing of Raw Materials and Extraction • 1 point Sourcing of Raw Materials - Leadership Extraction Practices • 1 point Material Ingredient Reporting - Material Ingredient Reporting • 1 point Material Ingredient Reporting - Material Ingredient Optimization • 1 point Environmental Product Declaration • 1 point

	Unit		SqF	Per Per Bundle		Soldier LnFt Per		Sailor LnFt per		Units Per		Lbs Per						
Stones & Bundling	Thickness	Bundle	Layer	Section	Stone	Layers	Sections	Unit	Layer	Bundle	SqFt	Layer	Bundle	SqFt	Bundle	Layer	Section	Bundle
Pickering Manufactu	Pickering Manufacturing / Beacon Hill Flagstone 6cm Almond Grove Fusion stocked in Ayr																	
Random Bundle		104.92	11.65			9	-	-	9.97	89.73	0.99	9.35	84.15	0.76	72	319.93	-	2,879.4
Large Rectangle	2¾" (60mm)	-	4.66	-	2.331	-	-	-	2.49	-	1.25		33.66	0.48	18		-	-
Small Rectangle	2¾" (60mm)	-	4.66	-	0.777	-	-	-	3.74	-	0.63		16.83	1.43	27		-	-
Square	2¾" (60mm)	-	2.33	-	1.554	-	-	-	3.74	-	1.25		33.66	0.72	27		-	-

Notes: Sold in full bundles only on a refundable skid. Beacon Hill 60mm is not intended for vehicular applications. All measurements are nominal. Important: A urethane rubber paver mat must be used to prevent scuffing. Contact your Unilock Territory Manager or call 1-800-UNILOCK for further information.*For custom options, please contact your Unilock Territory Manager.

* Addendum to Bundle Configurations coming soon!

APPLICATIONS

Pedestrian

Roof Deck

Wall pairing suggestion- U-CARA - matching colour and finish

*Paver Maintenance Tips:

- Equip plow scrapers and blades with shoes or high-density plastic blades to reduce the risk of damaging paver joints and the surface
- Only apply min. amount of de-icing salts necessary to melt the snow and ice. Remove excess salt after ice melts
- Regular cleaning routine should include sweeping or blowing loose debris from the pavement surface, and less frequently, deep cleaning with cleaning products and/or water
- Unilock pavers do not require sealing, however, some people choose to do so for aesthetic purposes

*Things to know:

Efflorescence is a naturally occuring calcium salt that can sometimes appear on the surface of concrete and clay products. Efflorescence does not affect the structural integrity of concrete, it is a purely aesthetic issue that typically disappears with no further intervention after a season of rainfall. If desired, the process can be accelerated by washing the surface with an Efflorescence Remover.